



L475W / LS475W+ Firmware Update (For A0E/A0N/A0P Regions)

Content *Ver. 20180423X*

1. Modify data overwrite procedure to prevent potential recording pause when SD card is full (Parking Surveillance 3.0 activated.)
2. Fix false alarm at 8~10km/h when speed warning is set to 140km/h and 160km/h.

