



# Firmware Update Guide

(Read before updating any firmware)

## Content

1. ONLY update firmware according to your region.  
  
A0E (EN11): North America, European region.  
A0P (EN08): Asia Pacific, Australia region.  
A0N (NO05): Norway.
2. For GPS equipped models, **mis-match firmware may cause faulty functions** such as not reporting traffic camera properly.
3. Re-update with proper firmware file if the previous update was made with wrong version.
4. Check firmware version from your dashcam to double check your firmware region.

Example:

LS500W\_CB160513-180130-EN11\_XXXXXXXXXX

**Orange:** Dashcam model name.

**Blue:** Version number in date form.

**Purple:** Firmware region.